

### Errata

"Motor control LSI with interpolation function, G9103C User's Manual" (DA70143-1/1E1) contains the error described below.  
Please confirm the following correction.

Page	Corrected point	Incorrect	Correct
148	8.8 External stop / simultaneous stop	3. The axis that STP signal input is enabled (RMD.MSP0 = 1) outputs a one-shot signal that is approximately 0.4 $\mu$ s when a stop caused by an error.	3. The axis that STP signal output at an error stop is enabled (RMD.MSPO=1) outputs a one-shot signal of approximately 0.4 $\mu$ s length from STP pin when an error stop occurs.

- End of document -